


Acatel AMS200 De-installation Report

Date :2015/1/6 ~ 2015/1/9

Day1 : Process pumping out




Day2: Chamber Cleaning



a. Chamber gate function check (Chamber vent at ATM→turbo running)






b. Leak check & base pressure




c. Turbo pump idle condition




d. Running data (2014/12/19)





e. Chamber Vent



f. Chiller function



Day3: De-installation



a. Connection









Day4: Moving out and crating

